



TO: Division File (C82-119N) DATE: 12-15-81  
FROM: BRAO Benning ☒ Information only  
SUBJECT: Cook Co (Gm) LAUSING / MR. FRANK - Follow-up - ☐ Response requested

On 12-15-81, myself and Jay Evans inspected the PCB excavation site, at the request of Jack Barnette. The purpose of the inspection was to determine the status of the clean-up operation, which is being conducted by Mr. FRANKS. Upon arrival at the site, no activity was observed, the excavated soil had been removed and the hole had not been filled in as yet. There was a pile of soil outside the restricted area which maybe the fill material. The excavation site was roped off and PCB warning labels had been posted.

RECEIVED

JAN 13 1982

ILL. E.P.A. - D.L.P.C.  
STATE OF ILLINOIS

RECEIVED

DEC 29 1981

EPA Region 5 Records Ctr.



392271

RECEIVED

JAN 19 1982

E.P.A. - D.L.P.C.  
STATE OF ILLINOISE.P.A. - D.L.P.C.  
STATE OF ILLINOIS